

Produktinformation



Forschungsprodukte & Biochemikalien



Zellkultur & Verbrauchsmaterial



Diagnostik & molekulare Diagnostik



Laborgeräte & Service

Weitere Information auf den folgenden Seiten! See the following pages for more information!



Lieferung & Zahlungsart

siehe unsere Liefer- und Versandbedingungen

Zuschläge

- Mindermengenzuschlag
- Trockeneiszuschlag
- Gefahrgutzuschlag
- Expressversand

SZABO-SCANDIC HandelsgmbH

Quellenstraße 110, A-1100 Wien

T. +43(0)1 489 3961-0

F. +43(0)1 489 3961-7

mail@szabo-scandic.com

www.szabo-scandic.com

linkedin.com/company/szaboscandic in





Instructions For Use MTM001-IFU

Rev. Date: Nov. 4, 2021

Revision: 3

Page 1 of 3

P.O. Box 3286 - Logan, Utah 84323, U.S.A. - Tel. (800) 729-8350 - Fax (435) 755-0015 - www.scytek.com

Mouse To Mouse HRP Ready-To-Use

Species of Origin: Goat

Antigen Specificity: Anti-Polyvalent (Mouse, Rat, Rabbit and Guinea Pig)


Enzyme Conjugate: Peroxidase

Chromogen Substrate: Diaminobenzidine (DAB)

Description:

Procedure:

- 1. Deparaffinize and rehydrate tissue section.
- 2. To reduce nonspecific background staining due to endogenous peroxidase, incubate slide in hydrogen peroxide for 10-15 minutes.
- 3. Wash 2 times in buffer.
- 4. If required, incubate tissue in digestive enzyme.
- 5. Wash 4 times in buffer.
- 6. Apply Super Block (blue cap), and incubate for 5 minutes at room temperature to block nonspecific background staining. **Note:** Do not exceed 10 minutes or there may be a reduction in desired stain.
- 7. Wash 1 time in buffer.
- 8. Apply Mouse to Mouse Block and incubate 10-60 minutes. Incubation time is dependent on the amount of endogenous Ig found in the tissue type.
- 9. Rinse 4 times in buffer.
- 10. Apply primary antibody and incubate according to manufacturer's protocol.
- 12. Wash 4 times in buffer.
- 13. Apply UltraTek Anti-Polyvalent (yellow cap), and incubate for 10-20 minutes at room temperature.
- 14. Wash 4 times in buffer.
- 15. Apply UltraTek HRP (red cap), and incubate for 10-20 minutes at room temperature.
- 16. Rinse 4 times in buffer.
- 17. Add 8 drops of DAB chromogen to one 5ml vial of DAB Substrate. Mix well and apply to tissue for 5 minutes.
- 18. Rinse 1 time in DI Water.









Instructions For Use MTM001-IFU

Rev. Date: Nov. 4, 2021

Revision: 3

Page 2 of 3

P.O. Box 3286 - Logan, Utah 84323, U.S.A. - Tel. (800) 729-8350 - Fax (435) 755-0015 - www.scytek.com

- 19. Apply DAB Chromogen/Substrate mixture and incubate for a second 5-minute period.
- 20. Rinse 3 times in DI water.
- 21. Counterstain and coverslip using a permanent mounting media.

Troubleshooting Guide

Overstaining:


- 1. Concentration of the primary antibody was too high or the incubation time was too long.
- 2. Temperature during incubation was too high.
- 3. Incubation time with UltraTek Anti-Polyvalent or UltraTek HRP was too long.

Nonspecific Background Staining:

- 1. Rinsing between steps was inadequate.
- 2. Tissue was allowed to dry with reagents on.
- 3. Folds in tissue trapped reagents.
- 4. Inadequate blocking with Mouse to Mouse Block.
- 5. Tissue contains endogenous biotin.
- 6. Antigen migrated in tissue.
- 7. Excessive tissue adhesive on slides.
- 8. Inadequate blocking with Super block.

Weak Staining:

- 1. Primary antibody concentration was too low or incubation time was too short.
- 2. Reagents are past their expiration date.
- 3. Inadequate removal of wash water between steps, resulting in dilution of reagents.
- Counterstain or mounting media were incompatible and dissolved the chromogen reaction product.
- 5. Room temperature was excessively cool.
- 6. The primary antibody does not recognize an antigen that survives fixation and embedding.
- 7. Excessive incubation with Super Block.











Instructions For Use MTM001-IFU

Rev. Date: Nov. 4, 2021

Revision: 3

Page 3 of 3

P.O. Box 3286 - Logan, Utah 84323, U.S.A. - Tel. (800) 729-8350 - Fax (435) 755-0015 - www.scytek.com

No Staining:

- 1. Steps were inadvertently left out.
- 2. There is no antigen in the tissue.
- 3. The primary antibody is not of mouse, rat, rabbit or guinea pig origin.
- 4. Chromogenic substrate has been replaced with another that is not intended for use with peroxidase.
- 5. One or more components of the kit have been inactivated.

